

HALEY & ALDRICH, INC. One Arizona Center 400 E. Van Buren St., Suite 545 Phoenix, AZ 85004 602.760.2450

#### **TECHNICAL MEMORANDUM**

3 April 2020 File No. 132473-005

TO: Florence Copper Inc.

Ian Ream, Senior Hydrogeologist

FROM: Haley & Aldrich, Inc.

Mark Nicholls, R.G. Sarah Cooper, P.E.

SUBJECT: Quarterly Temperature Logging Summary, Q1 2020

Production Test Facility Westbay Wells: WB-01, WB-02, WB-03, and WB-04

Florence Copper Inc., Florence, Arizona

#### Introduction

This Technical Memorandum presents the results of temperature logging of Production Test Facility (PTF) Westbay wells WB-01, WB-02, WB-03, and WB-04 during March 2020 for Florence Copper Inc. (Florence Copper) in Florence, Arizona.

Westbay wells WB-01, WB-02, WB-03, and WB-04 are located within the Underground Injection Control (UIC) Permitted Area of Review for UIC Permit R9UIC-AZ3-FY11-1 and were completed as Class III multi-level monitoring wells for the PTF (Figure 1).

Florence Copper contracted Southwest Exploration Services, LLC to perform temperature logging. Temperature logging was conducted to verify the absence of fluid movement through vertical channels adjacent to the well, in accordance with the 25 July 2019 UIC Permit Minor Modification.

### **Temperature Logging Results**

Florence Copper completed temperature logging of Westbay wells WB-01, WB-02, WB-03, and WB-04. Temperature runs were completed at least 4 hours apart after the wells had been shut in for 24 hours. The temperature logs were performed as listed below:

Well ID	Temperature Log Date	Temperature Log Run 1 Time	Temperature Log Run 2 Time
WB-01	3/13/2020	9:10 AM	1:10 PM
WB-02	3/13/2020	10:00 AM	2:00 PM
WB-03	3/13/2020	7:10 AM	11:10 AM
WB-04	3/13/2020	8:10 AM	12:10 PM

As-built diagrams of the Westbay wells are provided in Appendix A. The temperature logs are included in Appendix B. Daily average flow rates for the injection and recovery wells, and daily average water level elevations for the recovery and observation wells, are provided in Appendix C for the day temperature logs were conducted.

#### **Conclusions**

The temperature logging results for Westbay wells WB-01, WB-02, WB-03, and WB-04 show no anomalies that would indicate that there is flow behind the well casings. The temperature logs for each logging event reflect similar instrument readings for both the initial and secondary runs resulting in parallel temperature traces on each of the log records for the entirety of the well.

#### **Enclosures:**

Figure 1 – Well Locations


Appendix A – Westbay Well As-Built Diagrams


Appendix B – Q1 2020 Temperature Logs

Appendix C – Daily Average Flow Rates and Water Level Elevations

\\haleyaldrich.com\share\phx\_common\Projects\Florence Copper\132473 Florence Groundwater Permitting\Deliverables\Mar 2020 WB Temp Log Memo\2020-0403 TempLog\_WB Wells\_F.docx







## **APPENDIX A**

Westbay Well As-Built Diagrams

- 1. WELL REGISTRATION NO.: 55-227226
- 2. CADASTRAL LOCATION: D(4-9) 28 CAC
- 3. MEASURING POINT ELEVATION: 1479.34 FEET AMSL
- 4. I.D. = INSIDE DIAMETER
- 5. O.D. = OUTSIDE DIAMETER
- 6. PVC = POLYVINYL CHLORIDE
- 7. FRP = FIBERGLASS REINFORCED PLASTIC
- 8. ACD = ANNULAR CONDUCTIVITY DEVICE
- 9. DOWNHOLE EQUIPMENT INSTALLED BY WESTBAY **INSTRUMENTS**



PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA

WB-01 WESTBAY WELL **AS-BUILT DIAGRAM** 



- 1. WELL REGISTRATION NO.: 55-227227
- 2. CADASTRAL LOCATION: D(4-9) 28 CAC
- 3. MEASURING POINT ELEVATION: 1478.75 FEET AMSL
- 4. I.D. = INSIDE DIAMETER
- 5. O.D. = OUTSIDE DIAMETER
- 6. PVC = POLYVINYL CHLORIDE
- 7. FRP = FIBERGLASS REINFORCED PLASTIC
- 8. ACD = ANNULAR CONDUCTIVITY DEVICE
- 9. DOWNHOLE EQUIPMENT INSTALLED BY WESTBAY **INSTRUMENTS**



PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA

WB-02 WESTBAY WELL **AS-BUILT DIAGRAM** 



- 1. WELL REGISTRATION NO.: 55-227228
- 2. CADASTRAL LOCATION: D(4-9) 28 CAC
- 3. MEASURING POINT ELEVATION: 1478.99 FEET AMSL
- 4. I.D. = INSIDE DIAMETER
- 5. O.D. = OUTSIDE DIAMETER
- 6. PVC = POLYVINYL CHLORIDE
- 7. FRP = FIBERGLASS REINFORCED PLASTIC
- 8. ACD = ANNULAR CONDUCTIVITY DEVICE
- 9. DOWNHOLE EQUIPMENT INSTALLED BY WESTBAY **INSTRUMENTS**



PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA

WB-03 WESTBAY WELL **AS-BUILT DIAGRAM** 



Layout:

Printed: 8/31/2018 2:54

GITA

- 1. WELL REGISTRATION NO.: 55-227229
- 2. CADASTRAL LOCATION: D(4-9) 28 CAC
- 3. MEASURING POINT ELEVATION: 1479.79 FEET AMSL
- 4. I.D. = INSIDE DIAMETER
- 5. O.D. = OUTSIDE DIAMETER
- 6. PVC = POLYVINYL CHLORIDE
- 7. FRP = FIBERGLASS REINFORCED PLASTIC
- 8. ACD = ANNULAR CONDUCTIVITY DEVICE
- 9. DOWNHOLE EQUIPMENT INSTALLED BY WESTBAY **INSTRUMENTS**



PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA


WB-04 WESTBAY WELL **AS-BUILT DIAGRAM** 





## **APPENDIX B**


Q1 2020 Temperature Logs


Hala lafa conflor	Depth	Temperature (9:10 AM)											
Hole Information	1in:20ft	60 Deg F 100											
Well Name: WB-01		Temperature (1:10 PM)											
Survey Date: 03-13-20		60 Deg F 10											
Elevation: 1478.56 Ft Northing (NAD83): 746167.49		Differential Temperture											
Easting (NAD83): 847695.07		-2 Deg F											
Shut In Time: 24 Hours 0 Min													
Base of Lowermost USDW: 302 Ft													
Nat. Gamma													
0 API 400													
	WB-01 Temperature Evaluation												
3	0.0												
*													
\$													
	20.0												
3													
<b>\\</b>													
<b>\{</b>													
2	40.0												
Ş													
3													
NW.													
\$	(0.0												
3	60.0												
3													
3													
3													
3	80.0												
3													
3													
	100.0												
\$													
\$													
\$	120.0												
	12000												
\$													
2													
<b>\$</b>	140.0												
\$	140.0												
3													
3													
-	160.0												
}													
















	Depth	Depth Temperature (10:00 AM)									
Hole Information	1in:20ft	60 Deg F 100									
Well Name: WB-02		Temperature (2:00 PM)									
Survey Date: 03-13-20		60 Deg F 100									
Elevation: 1478.27 Ft		Differential Temperture									
Northing (NAD83): 746131.32											
Easting (NAD83): 847730.23		-2 Deg F 2									
Shut In Time: 24 Hours 0 Min	<b>I</b>										
Base of Lowermost USDW: 3  Nat. Gamma	00 Ft										
0 API	400										
		Temperature Evaluation									
<b>\{\}</b>	0.0										
\$											
{											
<b>\\</b>	20.0										
3											
\$											
2											
	40.0										
\$											
2											
\$											
	60.0										
3											
2											
3											
3	80.0										
₹	00.0										
3											
\$											
<b>S</b>											
Ş	100.0										
\$											
3											
2											
Ž	120.0										
\$											
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\											
\$	140.0										
3	140.0										
<b>\\ \\ \</b>											
5											
3	160.0										
\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	100.0										
3											
















Hala lafama etia a	Depth	Temperature (7:10 AM)											
Hole Information	1in:20ft	60 Deg F 100											
Well Name: WB-03		Temperature (11:10 AM)											
Survey Date: 03-13-20		60 Deg F 100											
Elevation: 1478.18 Ft Northing (NAD83): 746096.49		Differential Temperature											
Easting (NAD83): 847694.07		-2 Deg F 2											
Shut In Time: 24 Hours 0 Min													
Base of Lowermost USDW: 300	Ft												
Nat. Gamma	_												
0 API 40	0												
	WB-03	Temperature Evaluation											
3	0.0												
3													
<b>\\</b>													
2	20.0												
3													
<b>1</b>													
3	40.0												
3	40.0												
\$													
5													
	60.0												
3													
\$													
3													
Ž	90.0												
	80.0												
3													
3													
3													
3	100.0												
<													
3													
3													
5	120.0												
3	120.0												
\$													
\$													
3													
3	140.0												
}													
2													
3													
\$	160.0												
<b>\</b>	160.0												
















Hole Information	Depth	Temperature (8:10 AM)										
Hole information	1in:20ft	60 Deg F 100										
Well Name: WB-04		Temperature (12:10 PM)										
Survey Date: 03-13-20 Elevation: 1478.17 Ft		60 Deg F 100										
Northing (NAD83): 746131.41		Differential Temperature										
Easting (NAD83): 847659.81		-2 Deg F 2										
Shut In Time: 24 Hours 0 Min												
Base of Lowermost USDW: 300 Ft												
Nat. Gamma												
0 API 400												
	WB-04	Temperature Evaluation										
5	0.0											
Ž												
\$												
	20.0											
3												
2												
\$												
2	40.0											
Į į	40.0											
\$												
\$												
4												
\$	60.0											
3												
\$												
\$	80.0											
2												
\$												
\$												
\$	4000											
	100.0											
2												
5												
3												
3	120.0											
3												
3												
5												
3	140.0											
3	140.0											
\$												
3												
3												
_ {	160.0											
<del>                                    </del>												











## **APPENDIX C**

**Daily Average Flow Rates and Water Level Elevations** 

## TABLE 1 DAILY AVERAGE FLOW RATES FOR INJECTION AND RECOVERY WELLS DURING TEMPERATURE LOGGING

FLORENCE COPPER INC. FLORENCE, ARIZONA

Date	I-01	I-02	I-03	I-04	R-01	R-02	R-03	R-04	R-05	R-06	R-07	R-08	R-09
3/13/2020	56.11	47.01	49.03	46.11	22.01	18.96	13.19	27.01	19.24	16.88	15.07	17.08	74.93

#### Notes:

All measurements in gallons per minute.



# TABLE 2 DAILY AVERAGE WATER LEVEL ELEVATIONS DURING TEMPERATURE LOGGING

FLORENCE COPPER INC. FLORENCE, ARIZONA

Date	R-01	0-01	0-07	R-02	0-01	0-02	R-03	O-02	O-03	R-04	O-03	R-05	0-04	R-06	0-04	O-05	R-07	O-05	O-06	R-08	O-06	O-07	R-09
3/13/2020	1243.60	1252.15	1249.78	1209.72	1252.15	1249.79	1178.03	1249.79	1255.80	1124.18	1255.80	1189.93	1251.65	1195.14	1251.65	1251.93	1249.11	1251.93	1252.27	1238.37	1252.27	1249.78	1206.93

#### Notes:

All measurements in elevation above mean sea level.

